



Figure 1a: Damaged grout and cables at sensor D-2.



Figure 1b: View of irregular pre-split near Sta. 1326+00.